

Ⓛ Aufbauanleitung

Ⓛ Notice de montage

Ⓛ Montagehandleiding

Ⓛ Montážní návod

Ⓛ Szerelési útmutató

Ⓛ Montaj talimatları

Ⓛ Assembly instruction

Ⓛ Istruzione di montaggio

Ⓛ Instrukcja montażu







Ⓛ Navod na montaž

Ⓛ Instrucțiuni de montaj

Ⓛ Инструкция по монтажу

# 36-4275-82-001

## Wardrobe 2 doors- 65x100x201cm





# Service • Assistenza • Dienstverlening • Serwis Servis • Szerviz • Сервисная служба

Name • Nom • Nome • Naam • Nazwa • Jméno • Názov  
Név • Denumire • Isim • Название



Nr. • No. • N° • Č • Sz • Номер

Typ • Type • Tip • Tipus • Druh • Тіро • Тип




## Detail specification

| A.I. Nr. | Article Nr. | pcs |
|----------|-------------|-----|
| 1A       | 127410-82   | x1  |
| 2A       | 127420-82   | x1  |
| 3        | 027003-82   | x1  |
| 4        | 027210-82   | x1  |
| 5        | 027002-82   | x1  |
| 6        | 027220-82   | x1  |
| 7        | 027001-82   | x1  |
| 8        | 027310-82   | x3  |
| 9        | 027520-82   | x1  |
| 10       | 027004-32   | x1  |
| 11       | 027610-82   | x2  |
| 12       | 027621-32   | x2  |
| 13       | 027622-32   | x2  |
| 14       | 027630-32   | x2  |
| 15       | 027640-52   | x2  |
| 16       | 027005-82   | x2  |
| 17       | 1-000063-57 | x1  |
| 18       | 027710-52   | x2  |




## Fitting specification


| A.I. Nr. | Article Nr. | Dimensions | pcs     |
|----------|-------------|------------|---------|
| a        | 1-000046-07 | 6x34       | x32     |
| b        | 1-000013-00 | 8x40       | x48     |
| c        | 1-000047-07 | 5,8x19     | x8      |
| d        | 1-000048-07 | 15x12      | x32     |
| e        | 1-000049-07 | 5,8x8      | x8      |
| f        | 1-000050-00 | 8x70       | x4      |
| g        | 1-000127-07 | M4x20      | x4      |
| h        | 1-000052-07 | 18x25      | x4      |
| i        | 1-000053-07 | 5/5        | x12     |
| j        | 1-000054-57 | 31x25x15   | x2      |
| k        | 1-000037-07 | 3x15       | x28     |
| l        | 1-000055-07 | 3x20       | x7      |
| m        | 1-000056-07 | 14x19      | x7      |
| n        | 1-000057-07 | 3,5x40     | x8      |
| o        | 1-000058-07 | 600        | x2 sets |
| p        | 1-000059-07 | D26        | x6      |
| q        | 1-000060-07 | 37         | x6      |
| r        | 1-000061-57 | 19x10      | x8      |
| s        | 1-000062-07 | 3x20       | x30     |
| t        | 1-000111-57 | D18        | x16     |




1-000001=




1.




2.




3.




4.




5.




6.





7.




8.







13.





14.



15.




16.




17.

17.1.



17.2.



17.3.

